

1124 AND 1124A WESTWIND SERVICE BULLETIN INDEX

SB Number	Rev	Type	Date	SN Effective	Title
WW-24-1A			09/15/1976	187, 188, 189	Improved Cooling of E.C.U. from Ram Air Inlet to E.C. Bearing (External Area) and Modifying Ram Air Exhaust Port to Different Shape
WW-24-2			09/08/1976	187, 188, 189, 192	Bolts Replacement on Thrust Reverser Controls Installation
WW-24-3	1		05/23/1978	154, 181, 187-201, 204,206, 208	Installation of Frame Block for External Ground to Starter-Generator
WW-24-4B	1		05/23/1978	154, 181, 187-209, 215	Inspection of Generator Control Units
WW-24-5	1		05/23/1978	154, 181, 187-205, 207	Engine Driven Hydraulic Pump Bypass Port Plug Replacement
WW-24-6			04/11/1977	154, 181, 187-200	Chafing of Tubes in L.H. Engine Pylon and Relocation of Nitrogen Gauges and Charging Valves
WW-24-7A			10/18/1977	154, 181, 187-200	Aft Engine Mount Fitting Assembly Inspection
WW-24-8A			07/15/1977	154, 181, 187-194, 196	Replacement of Nuts and Washers on Forward Engine Mount Attachment Bolts
WW-24-9	1		05/23/1978	154, 181, 187-212, 215	Modification of Main Landing Gear
WW-24-10	1		05/23/1978	154, 181, 187-210, 215	Chafing of Tubes near R.H. Engine Pylon
WW-24-11			12/30/1977	187-193	Replacement of Aileron Control Chain Assy P/N 3533516-1 and Sprocket P/N 2533049-501 in Flight Control Columns
WW-24-12			10/18/1977	154, 181, 187-205, 207,209, 215	Inspection of Generator Circuit Resistors R-11 and R-12
WW-24-13			08/07/1978	187-199, 201	Replacement of Throttle Retarder Feedback Control
WW-24-14			09/08/1989		Inspection of Horizontal Stabilizer Hinge Fitting (CANCELED)

SB Number	Rev	Type	Date	SN Effective	Title
WW-24-15	1		12/05/1978	154, 187-229, 232	Power Brake Valve - Replacement of Poppet Retainer Pin P/N 117W50D12
WW-24-16			05/15/1979	152, 154, 181 & any 1123 converted to an 1124 not in compliance with SB WW-19	Aft Pressure Bulkhead Modification
WW-24-17A	1		03/31/1980	152, 154, 181, 187-260, 262-264, 266-269	Installation of Additional Rivets in 25 Percent Wing Spar
WW-24-18	1		03/26/1980	240-260, 262-264, 266	Installation of Bolts in Floor, Near Fus. STA 269
WW-24-19			05/15/1980	240-275	Inspection of Aileron Control Pulley P/N 3533032-1
WW-24-20	1		11/21/1980	239-298 except 241, 252, 257, 261, 264, 265, 290, 294, 295, 297	Part I - Inspection of Electrical Wires for Chafing Against Upper Hot Liquid Container in Galley; Part II - Rerouting of Electrical Wiring Behind Hot Liquid Container Compartments of Galley P/ N CMA 521288
WW-24-21			04/30/1981	152, 154, 174, 181, 187- 309, 311-316, 318, 320- 324	One Time Inspection of Forward Engine Mount Attaching Bolts for Sufficient Torque
WW-24-22			09/18/1981	152, 156, 174, 181, 185- 335	Inspection of Pilot and Copilot Seat Attachment
WW-24-23			03/11/1981	152, 154, 174, 181, 185, 187- 315 except 294, 296, 297, 309, 310, 314	Replacement of Audio Load Resistor, R-61
WW-24-24	2		07/30/1982	219, 221, 224, 228, 230, 231, 234, 236, 238, 242, 246, 248-251, 256-261, 263, 265-267, 270-363	Rework of Ballast/Jack Adapter Mounting

SB Number	Rev	Type	Date	SN Effective	Title
WW-24-25			02/12/1982	174, 290, 295, 299-309, 315, 317-319, 322, 324, 328, 330, 334, 335, 337-346, 351, 352	Rockwell-Collins Service Bulletin No. 3 for CTL-20, CTL-60 and CTL-90 Controls, and Service Bulletin No. 4 for CTL-30
WW-24-26			06/15/1982	152, 154, 174, 181, 185-238, 240-294, 296-298, 310-314, 316, 317, 320, 321, 323, 325-327, 329, 331-333, 336, 347, 354, 357, 360, 362, 363, 366, 367, 370-372, 375, and 378	Removal of Zener Diodes and Resistors from Air Data Power Supply Circuits
WW-24-27			07/06/1982	152, 154, 174, 181, 185-373	General Electric DC Starter Generator Model 2CM504D2D Limitations and Ammeter Markings
WW-24-28A	1		06/14/1985	All	Landing Gear-Inspection of Nose Landing Gear Outer Strut-Body Forging
WW-24-29			11/04/1983	All prior to 389 with FGC/APS-80 glideslope systems	Prevention of Improper Flight Director Glideslope Display
1124-22-001			02/29/1984	152, 154, 174, 181, 185-384	Navigation - Alternate Location for G/A (Go Around) and Vertical Sync Buttons
1124-28-002	1		04/12/1985	1124/1124A, s/n's 181, 226, 228, 230, 231, 235-403, 405, 407, 409; 1124, s/n's 152 174, 185-225, 227	Inspection of Fuel Sump Check Valve Lever and Installation of Manual Lever Handle Stop
1124-27-003			11/21/1986		Flight Controls - Flap Vane Inspection (CANCELED)
1124-57-004	1		09/09/1985	All	Drain Holes in Wing Trailing Edge Structure
1124-52-005			01/04/1985	152, 154, 174, 181, 185-278	Doors - Improved Main Baggage Compartment Door Warning SwitchInstallation

SB Number	Rev	Type	Date	SN Effective	Title
1124-25-006			01/04/1985	All thru 414	Cockpit Panels - Installation/Rework
1124-52-007			01/04/1985	152, 174, 181, 185-387, 389-394	Main Cabin Door Lower Flapper Retract Spring
1124-24-008	2		07/29/1985	152, 174, 181, 185-425 except 413, 416, 418, 421-424	Installation of Larger Capacity Priority Bus Diodes and Elimination of Ground Pressure Bumps
1124-32-009			01/15/1985	295 & subs	Gear Warning Horn Automatic Disable
1124-33-010	2		08/12/1985	All thru 414	Emergency and Entrance Light Module Corrections
1124-39-011	1		06/14/1985	All prior to 259	Overhead Panel Access and Alignment Improvement and/or Retrofit
1124-27-012			06/14/1986		Flap Actuator - Improvement and Repair (CANCELED)
1124-23-013			02/11/1985	152, 154, 174, 185-391	VHF COM and Audio System Conformity
1124-29-014	1		02/18/1986	All prior to 439	Emergency Hydraulic Pump Protective Cover Installation
1124-34-015	1		08/23/1985	All	VOR/LOC Antenna Bonding and Phasing
1124-23-016	2		05/23/1986	All thru 426	Installation of Additional and Improved Static Wicks
1124-27-017			10/31/1985	152, 154, 174, 181, 185- 403, 405, 407, 409	Flight Controls - Modification of Rudder Servo Trim Tab
1124-22-018			04/15/1985	295-425	Autoflight - Nuisance Autopilot Disengagement
1124-52-019A	A		08/12/1985	All prior to 385 except 376	Improved Cabin Entrance Door-Stay
1124-55-020	2		08/08/1988	All	Horizontal Stabilizer Aft Spar Splice Fitting P/N 453005-501 (Hinge Assembly) Inspection

SB Number	Rev	Type	Date	SN Effective	Title
1124-55-021	3		10/21/1988	152, 174, 181, 185-408, 410-412, 414, 415, 417, 419, 420, 422, 425	Horizontal Stabilizer Assembly - Inspection, Repair and Improvement (AFC 2037)
1124-26-022	2		11/28/1990	152, 154, 174, 181, 185-237, 239-253, 255-280, 282-313, 315, 318-324, 326-365, 367- 370, 382-385, 387-408, 410 and subs	Fire Protection - Addition of Sonalert Horn to Fire Warning System
1124-34-023			12/09/1985	All prior to 423	Navigation - Elimination of Improper Mach Warnings
1124-22-024	1		06/14/1985	152, 174, 181, 187-406 with Collins 590A3K-1 or 590A3J-1 ADC	Elimination of FCS 105 Altitude Mode Transition Errors
1124-22-025A	A		11/17/1986	295-425, 427-437	Autoflight - Elimination of 1124A Overspeed Warning Failures
1124-53-026			04/18/1985	All prior to 426 except 413,416, 418, 421, 423, 424	Closure of Tail Cone Vent Holes
1124-34-027			04/18/1985	295-426 with Global 3B VLF Nav	Enable GNS-500A Series 3B Bank Command Option for Flight Director System
1124-21-028			08/23/1985	All prior to 427 except aircraft with AC inverters installed at sta 328-340	Reduction of Cooling Air Volume to Both DC Contactor Boxes and Closure of Air Outlet Near Battery Installation
1124-21-029			04/24/1985	All prior to 427 with long range fuel tank provisions	Baggage Compartment Heat System
1124-32-030	1		09/18/1985	All prior to 428 except 413, 416, 418, 421, 423, 426	Rerouting of Nose Landing Gear Wiring Harness

SB Number	Rev	Type	Date	SN Effective	Title
1124-22-031			06/28/1985	152, 154, 174, 181, 185-378	Vertical Gyro Fast Erect Switch
1124-22-032			06/28/1985	295 & subs	Collins VNI-80 (), Vertical Navigation Indicator Altitude Preslave Switch
1124-23-033	1		07/05/1985	240-347	400 Cycle Hum in VHF COM Modulation
1124-33-034	1		06/14/1985	All prior to 426 except 413, 416, 418, 421, 423, 424	Logo Light Modification
1124-28-035	1		06/14/1985	All prior to 426 except 413, 416, 418, 423, 424	Elimination of Erratic Fuel Quantity Indications
1124-30-036	1		12/20/1985	All	Ice and Rain - PART I-Windshield Heat Control Wiring Modification; PART II-Windshield Heat Cycling Contractor Inspection and/or Replacement
1124-52-037	1		06/14/1985	All prior to 426 except 416, 418, 421, 423	FWD Baggage Door - Positive Hold-Open Provision
1124-23-038	1		06/09/1986	243-345, 347, 349-352, 354, 355, 357-379, 381-391, 393, 396-401	Stereo Configuration Errors
1124-34-039			07/14/1986	All prior to 413 with FPA-80	Navigation FPA-80 Option Improvements
1124-52-040			04/22/1992	All	Doors - Door Handle Warning Switch Installation and Improved Door Wire Retract Tube Installation (AFC 2068)
1124-23-041			06/14/1985	290, 295-348, 350-375	Bypass of CTL(XX) Control Head Volume Controls
1124-56-042A	A		09/10/1986	All	Windows - Repair of the Inner Windshield Panel
1124-24-043	2		01/08/1992	All prior to 431 except 413, 416, 418, 421, 423, 426, 428, 429	Starter/Generator - Field Circuit Wiring Modification

SB Number	Rev	Type	Date	SN Effective	Title
1124-34-044	1		10/07/1985	All thru 411 except 187, 188, 189, 191, 192, 197, 215, 290	331A-9G HSI Distance Display Improvements
1124-32-045	1		12/02/1985	All prior to 431 except 154,413, 416, 418, 421, 423, 426, 428, 429	Inspection of MLG Actuating Cylinder Inboard Rod-End Bearings and Attach Bolts
1124-23-046			09/09/1985	240-390 with flight phone R/T located in nose compartment at sta 15.00	Replacement and Relocation of Flight Telephone Antenna
1124-34-047	1		12/11/1991	All	Navigation - Static Source Improvement for Copilot's Altimeter
1124-34-048	1		12/09/1985	All prior to 420	Collins VNI-80 Vertical Navigation Indicator Operation Improvement
1124-34-049			12/02/1985	All prior to 413 except 154	Navigation - Radar Waveguide Pressurization and Installation of Silica Gel Container Assembly
1124-23-050			01/03/1986	SN specified in Service Bulletin	Communications - VHF COM 3 System Improvements
1124-23-051			12/02/1985	All	Communications - Stereo System Improvements
1124-34-052			01/31/1986	All except 437 & 439	Navigation - Glideslope Raw Data Scalloping
1124-34-053			12/02/1985	All	Navigation - Compass and ADF/RMI System Improvements
1124-24-054	1		01/10/1986	All prior to 428 except 413, 416, 418, 421, 423, 426	Electrical Power - Fuel Quantity and ITT Gauges to Priority Bus
1124-34-055			01/22/1986	1124, all s/n's prior to 426 with LRN-85 installed as #1 system; 1124A, s/n's 295-442	Navigation - FMS-90/LRN-85 Improvements

SB Number	Rev	Type	Date	SN Effective	Title
1124-22-056			12/02/1985	All prior to 364	Autoflight - Correction of Flight Director Annunciator Self-Test Circuit
1124-34-057	1		01/31/1986	251, 259 & subs with Collins 639U-1 NCS power supply; 187-250 & 252-258 with existing LT-52A power supplies	Navigation - NCS-31 Display and Logic Power Supply Improvements
1124-33-058	2		06/12/1986	All	Lights - Corrections and Improvements to Dimming System for Avionics Digital Displays
1124-21-059			05/01/1996	All except 422, 424, 425	Air Conditioning - Cabin Automatic Temperature Control System Shielded Wire Installation and Cabin Temperature Sensor Relocation
1124-33-060			12/09/1985	All	Lights - Instrument Light Intensity and Dimmer Balance
1124-27-061			05/09/1986	All	Flight Controls - Wing Flap Actuators, Improvement/Repair
1124-27-062			12/23/1985	All prior to 400	Flight Controls - Speed Brake - Inadvertent Deployment
1124-25-063A	A		04/10/1987	All s/n's equipped with EL-M-100/28C & EL-M-100/28EX hot liquid containers	Equipment/Furnishings - Hot Liquid Container
1124-34-064	1		02/16/1987	1124, all s/n's; 1124A, s/n's 295-390	Navigation - Repeat VOR/LOC Switching Improvements
1124-24-065			01/10/1986	All prior to 437 except 418, 423, 426, 429, 431, 432, 435	DC Electrical System - Remote Circuit Breaker Random Tripping
1124-30-066A	1		10/17/1986	All thru 426	Ice and Rain Protection AOA and SAT TAS Probes Heat Wiring Improvement

SB Number	Rev	Type	Date	SN Effective	Title
1124-34-067			01/08/1986	1124, all s/n's with nose deck mounted vert. gyro(s);1124A, s/n's 295-426 without split gyro installation	Navigation - Retrofit of Collins Vertical Gyro(s) and Improved Vertical Gyro Mounting
1124-53-068			02/05/1986	All	Doors - Nose Gear Trunnion Access Door Installation
1124-33-069			01/31/1986	152, 154, 181, 187-400	Lights - Change in Power Source for Cabin Lighting System
1124-34-070			01/15/1986	All s/n's using "EField" antennas for VLF nav systems	Navigation - VLF/Omega Receiver Performance Improvement
1124-34-071	1		06/30/1987	SN specified in Service Bulletin	Navigation - Copilot's Altimeter Part Number Changes
1124-22-072A	A		09/12/1986	All prior to 437 except 418, 423, 426, 429, 431, 432, 435	Autoflight - Elevator and Rudder Servo Idler Arm - Install New Attach Bolts
1124-23-073			01/15/1986	All s/n's with optioal DMQ-18-1A ELT antenna	Communications - DMQ-18-1A ELT Antenna Hum Correction During High Speed Flight
1124-23-074	1		05/23/1986	All s/n's with a Wulfsburg Flightfone III, IV, V or VI	Communications - Radio Telephone Improvements and Corrections
1124-24-075	1		05/23/1986	All s/n's with a voice recorder and/or Flight Data Recorder installed	Electrical Power - Cockpit Voice and Flight Data Recorder Bus Change
1124-21-076A	A		06/30/1987	All s/n's prior to 438 except 418, 423, 426, 429, 431, 432, 435	Air Conditioning - Improved Cap Assembly for Unused Port on Air Gasper P/N 2708 "WEMAC"
1124-35-077			02/07/1986	All	Oxygen - Cabin Altitude Pressure Switch - Remote Test Connection Installation

SB Number	Rev	Type	Date	SN Effective	Title
1124-28-078			06/29/1987	152, 154, 174, 181, 185 & subs	Fuel - Fuel Status System Improvements
1124-22-079			01/08/1986	295-390 with a singal or dual flight director system; 392 & subs with a singal or dual flight director system	Autoflight - Establish Linear Deviation Steering Command to Autopilot
1124-23-080			01/12/1987	349, 375-377 & 379-442	Communication - Elimination of Cross-Side Transmitter Sidetone
1124-23-081A	A		03/17/1986	154, 181, 187 & subs	Communications - Alternate VHF COM 1 Antenna
1124-23-082			01/31/1986	All	Communications - Replacement of Audio Selector Panel Volume Controls
1124-28-083			02/14/1990		Fuel - Modification of Fuel Transfer Pump (CANCELED)
1124-xx-084					Not Issued
1124-25-085			02/24/1986	All	Equipment/Furnishings - Crew Seat Slide Release Arm Assembly Improvement
1124-27-086			04/10/1987	All thru 412, 414, 415, 417, 419, 420, 422, 424, 425, 427, 430	Flight Controls - Inspection and/or Replacement of LH and RH Elevator Reducer Tube Collars
1124-28-087			04/04/1986	1124, s/n's 152, 174, 181, 185, 186, 226, 228, 230, 231, 235-294 & all s/n's post SL WW- 2434; 1124A,	Fuel - Removal of EMI Filters from Intertechnique Boost Pump Circuit
1124-11-088A	A		03/20/1987	All prior to 438 except 239	Placards & Markings - Overwing and Single Point Fueling Filler Ports Placard Replacement
1124-21-089			04/06/1987	All	Air Conditioning - Incorporation of Refrigeration Unit Overtemperature Protection System (OPS)

SB Number	Rev	Type	Date	SN Effective	Title
1124-30-090	1		09/08/1989	All prior to 282 post SL WW-2444, 283 & subs	Ice and Rain - NAC/ENG Anti-Ice - Switch Reliability (AFC 2071)
1124-71-091	2		06/02/1989	All prior to 441, except 432, 435, 438	Power Plant - Forward Engine Mount Fasteners - Inspection/Replacement (AFC 2065)
1124-57-092	1		06/30/1987	All	Wings - Flap Hinge Fasteners - Inspection/Replacement
1124-79-093			03/14/1988	All	Oil - Engine - Oil Pressure Indication Installation (AFC 2066)
1124-32-094			12/16/1987	All except 432, 435, 438, 441, 442	Landing Gear - Selector Valve Arm - Secure Roll Pin (AFC 2063)
1124-27-095			04/04/1988	All	Flight Controls - F44-14 Rod-Ends - Inspection/Replacement
1124-32-096			04/04/1988	All	Landing Gear - F44-14 Rod-Ends - Inspection/Replacement
1124-55-097			02/03/1989	All except 441	Horizontal Stabilizer Scissors Assembly P/N 453516-501 or -503 Inspection
1124-28-098			02/15/1989	All prior to 391	Fuel - Preventing Fuel Spillage through Vent System During Refueling or Transfer Operations (AFC 2074)
1124-34-099			09/01/1989	All	Navigation - Pitot Head - Exchange of Certain Aero Instruments Company P/N PH1100 Pitot Heads
1124-27-100	2		04/24/1991	All	Flight Controls - Replacement of Left and Right Aileron Control Rod Assemblies P/N 513506-503
1124-53-101	1		02/04/2000	All	Fuselage - Enlarge Existing Wing Attachment Access Holes in the Aft Pressure Bulkhead at Fuselage Station 269.879 for Structural Inspection (AFC 2075)
1124-53-102			10/09/1991	All	Fuselage - Drain Valves Installation in the Fuselage Lower Skin (AFC 2076)
1124-11-103			11/26/1990	All	Placards and Markings - Towing Instruction Placard Replacement (AFC 2074)

SB Number	Rev	Type	Date	SN Effective	Title
1124-27-104	2		06/17/1992	All	Flight Controls - Relocate Bonding Jumpers Between Horizontal and Vertical Stabilizers and Control Surfaces (AFC 1056)
1124-32-105	1		05/08/1991	All except 152, 185, 186	Landing Gear - Nose Landing Gear Door Modification (AFC 1055)
1124-28-106			05/08/1991	All	Fuel - Tip Tank - Sealing of Float Switch Wire Conduit
1124-55-107			09/28/1994	All s/n's post SB 1124-55-021	Stabilizers - Horizontal Stabilizer Lower Scissor Fitting Replacement (AFC 2073)
1124-21-108			05/15/1991	All	Air Conditioning - Water Separator Duct Clamping Improvement (AFC 2077)
1124-34-109			12/11/1991	394-422, 425	Navigation - Static Port Tubing Slope Inspection and Correction
1124-32-110			03/11/1992	All	Landing Gear - Emergency Gear Down Handle
1124-78-111			05/27/1992	All	Exhaust - Thrust Reverser Fault Test Switch Reliability Improvement (AFC 2084)
1124-54-112			10/07/1992	All	Nacelles - Cowl Door Corrosion - Inspection, Prevention and Repair
1124-56-113			06/22/1994	All	Windows - Improved Cockpit Side Window Installation
1124-53-114			10/28/1992	All	Fuselage - Floor Panel Insulation Removal
1124-21-115	1		08/03/1994	259 & subs	Air Conditioning - Improve Operation of Cabin Auto Temp System
1124-32-116			11/23/1994	All	Landing Gear - Nose Wheel Steering System - Steering Control Cable Drum
1124-25-117			01/27/1993	All	Equipment/Furnishing - Passenger Life Vest Accessibility
1124-53-118			01/26/1994	All	Fuselage - Frame Reinforcement Repair Installation
1124-26-119			06/23/1993	All	Fire Protection - Inspection of Aft Fire Extinguisher Line in Left and Right Engine Pylons
1124-24-120			06/22/1994	All	Electrical Power - Improved Ground Returns

SB Number	Rev	Type	Date	SN Effective	Title
1124-33-121			05/25/1994	All	Lights - Cabin Fluorescent Lighting Support System Improvement
1124-33-122			06/15/1994	All	Lights - Tip Tank Strobe Light Wiring Conduit
1124-53-123			09/21/1994	All	Fuselage - Drainage Under Cabin Deck
1124-55-124			07/12/1995	All s/n's post SB 1124-55-021	Stabilizers - Horizontal Stabilizer Upper Scissor Fitting Replacement (AFC 2097)
1124-30-125			05/14/1997	187-285	Ice and Rain Protection - Windshield Wiper System Park Circuit Modification
1124-57-126			07/26/1995	All	Wings - Leading Edge Extension Drains
1124-24-127			09/25/1996	All	Electrical Power - Replacement of Remote Control Circuit Breakers, P/N 6141H168
1124-27-128			10/30/1996	All prior to 283	Flight Controls - Replacement of Flap Comparator Gear Box Assemblies with Linear Potentiometer Assemblies
1124-27-129			06/12/1995	All	Flight Controls - Aileron Push-Pull Tube and Guide Roller Inspection
1124-55-130	1		03/14/2001	All	Stabilizers - Empennage Fairing Installation
1124-33-131			01/24/1996	All	Lights - Upgrading "66" Series Fluorescent Lighting Systems with AL-"12" Series Lamps
1124-29-132			09/11/1996	All	Hydraulic Power - Hydraulic Fuse Functional Test
1124-27-133	1		05/28/1997	All	Flight Controls - Inspection of Horizontal Stabilizer Trim Actuator
1124-78A-134			09/15/1999	All	Exhaust-Thrust-Reverser-Secondary Latch Solenoid Switch Check
1124-26-135	1		10/26/1999	All	Fire Protection - Fire Detection System - Press-To-Test Switch Reliability Improvement
1124-27-136			09/01/1997	All	Flight Controls - Horizontal Stabilizer Trim Actuator Jackscrew Assembly Replacement
1124-35-137		MAN	09/23/2002	All	Oxygen -Oxygen Shut-Off Valve -Replacement of Existing Valve With Slow Opening Valve

SB Number	Rev	Type	Date	SN Effective	Title
1124-54A-138			03/29/2001	All	Nacelle/Pylons - Engine Inlet Cowl and Aft Nacelle - Verification of Approved Installed Attachment Bolts
1124-32-139			03/05/1998	All	Landing Gear - Inspection & Modification of Upper & Lower Steering Bracket Assemblies (AFC 5613)
1124-29A-140			08/15/1998	All	Hydraulic Power-Indication-Installation of Independent Circuit Breaker for Low Pressure Warning
1124-32-141			06/11/1998	152-353, 360	Landing Gear - Steering - Replacement of 45 Degree Steering Brackets with 58 Degree Steering Brackets
1124-30A-142			05/24/2000	All	Ice and Rain Protection - Windows and Windshields - Inspection of Windshield Wiper Arm
1124-21-143			09/17/2001	All	Air Conditioning - Safety Outflow Solenoid Valve - Installation of Jumper Wire for Improved Electrical Grounding
1124-27-144		MAN	03/17/2004	All	Flight Controls - Aileron - X-Ray Inspection of Left and Right Aileron Control Rod Assemblies P/N 513506-503RD and 503RE
1124-27A-145			03/24/2000	297, 304, 400-410	Flight Controls - Aileron - Radiographic Inspection of Left and Right Aileron Rib to Spar Connections
1124-35A-146		MAN	11/14/2003	All	Oxygen - Pressure Reducer/Regulator Assembly - Inspection of High Pressure Inlet Boss
1124-27A-147			08/28/2000	All	Flight Controls - Horizontal Stabilizer Trim Actuator - Inspection of the Jackscrew Assemblies
1124-55-148	1	MAN	09/17/2003	All	Stabilizers - Vertical Stabilizer - Inspection and Repair Of Aerodynamic Fairings Due to Loose or Missing Rivets
1124-32-149			10/29/2001	All	Landing Gear - Main Landing Gear Assembly - Introduction of Improved Trunnion Attaching Hardware
1124-55-150	1	MAN	06/23/2003	All	Stabilizers-Rudder- Inspection For Fatigue Cracks

SB Number	Rev	Type	Date	SN Effective	Title
1124-27-151	1	REC	09/28/2004	All	Flight Controls - Inspection of Trim Actuator Rod End Bearings and Replacement of Existing Bushings with Flanged Bushing
1124-29-152		REC	03/02/2004	All	Hydraulics - Inspection of Hydraulic Tube Assemblies Below Hydraulic Reservoir at the Drain Box Cutouts
1124-27-153		MAN	11/03/2005	All	Flight Controls - Inspection and Replacement of Inboard Flap Actuators P/N 193544-1
1124-24A-154		MAN	03/22/2004	All	Electrical Power Overhead Electrical Panels - One Time Inspection Of Wire Bundle Routed Above The "No Smoking - Fasten Seat Belt" Sign For Chaffing
1124-28-155	2	MAN	12/22/2008	All	Fuel - Distribution - RCCB Replacement in DC Contactor Box
1124-27-156	1	MAN	5/1/2009	All	Flight Controls - Aileron – Replacement of Left and Right Aileron Control Rod Assemblies P/N 513020-501 AND -501RE